


Diagram Package


Publication Part No. 246617

December 1992

Supersedes April 1992



# KODAK X-OMAT 480 RA Processor



HEALTH SCIENCES

#### PLEASE NOTE

The information contained herein is based on the experience and knowledge relating to the subject matter gained by Eastman Kodak Company prior to publication.

No patent license is granted by this information.

Eastman Kodak Company reserves the right to change this information without notice, and makes no warranty, express or implied, with respect to this information. Kodak shall not be liable for any loss or damage, including consequential or special damages, resulting from the use of this information, even if loss or damage is caused by Kodak's negligence or other fault.


#### CAUTION





This equipment includes parts and assemblies sensitive to damage from electrostatic discharge. Use caution to prevent damage during all service procedures.


## Table of Contents


Description	Page
Circuit Diagram, S/N 1001 - 1042, 1 of 2 .....	3
Circuit Diagram, S/N 1001 - 1042, 2 of 2 .....	4
Circuit Diagram, S/N 1043 and above, 1 of 2 .....	5
Circuit Diagram, S/N 1043 and above, 2 of 2 .....	6
Wiring Diagram, S/N 1001 - 1042, 1 of 4 .....	7
Wiring Diagram, S/N 1001 - 1042, 2 of 4 .....	8
Wiring Diagram, S/N 1001 - 1042, 3 of 4 .....	9
Wiring Diagram, S/N 1001 - 1042, 4 of 4 .....	10
Wiring Diagram, S/N 1043 and above, 1 of 4 .....	11
Wiring Diagram, S/N 1043 and above, 2 of 4 .....	12
Wiring Diagram, S/N 1043 and above, 3 of 4 .....	13
Wiring Diagram, S/N 1043 and above, 4 of 4 .....	14
Transformer Connection Chart and Diagrams 1 of 2 .....	15
Transformer Connection Chart and Diagrams 2 of 2 .....	16
















WIRING DIAGRAM  
480 RA SN 1001 TO 1042  
SHEET 2 OF 4









WIRING DIAGRAM  
480 RA SN 1001 TO 1042  
SHEET 4 OF 4










WIRING DIAGRAM  
480 RA S/N 1043 TO -  
SHEET 4 OF 4

TRANSFORMER CONNECTION CHART AND DIAGRAMS


CHART			
POWER SYSTEM	NOMINAL SUPPLY VOLTAGE	FREQUENCY (Hz)	CONNECTION DIAGRAM
	120/200	60 SEE NOTE	A
	127/220	50 SEE NOTE	B
	220/380	50 SEE NOTE	K
	230/400	50 SEE NOTE	L
	240/415	50 SEE NOTE	M
	200	50/60 SEE NOTE	C
	220	50/60 SEE NOTE	D
	230	50/60 SEE NOTE	E
	240	50/60 SEE NOTE	F

NOTE: SET THE SWITCH AT THE REAR OF THE DEVELOPER AND FIXER REPLENISHMENT PUMPS (B3 AND B4) TO THE CORRECT FREQUENCY.

CHART			
POWER SYSTEM	NOMINAL SUPPLY VOLTAGE	FREQUENCY (Hz)	CONNECTION DIAGRAM
	100/200	50/60 SEE NOTE	G
	120/240	50/60 SEE NOTE	H
	200	50/60 SEE NOTE	J
	120/200	60 SEE NOTE	N
	127/220	50 SEE NOTE	O
	220/380	50 SEE NOTE	P
	230/400	50 SEE NOTE	R
	240/415	50 SEE NOTE	S



TRANSFORMER  
CONNECTION CHART  
AND DIAGRAMS  
SHEET 1 OF 2





**BLANK PAGE**

Health Sciences  
EASTMAN KODAK COMPANY  
Rochester, New York 14650

Kodak and X-Omat are trademarks.

*The new vision of Kodak*

